




Kods	mm	"	Skice
A50A	13	1/2	
A75/50A	19 - 13	3/4 - 1/2	
A75A	19	3/4	
A100A	25	1	
A125A	32	1 1/4	
A150A	38/40	1 1/2	
A200A	50	2	
A250A	63/65	2 1/2	
A300A	75	3	
A400A	100	4	
F50A	13	1/2	
F75/50A	19 - 13	3/4 - 1/2	
F75A	19	3/4	
F100A	25	1	
F125A	32	1 1/4	
F150A	38/40	1 1/2	
F200A	50	2	
F250A	63/65	2 1/2	
F300A	75	3	
F400A	100	4	
E50A	13	1/2	
E75/50A	19 - 13	3/4 - 1/2	
E75A	19	3/4	
E100A	25	1	
E125A	32	1 1/4	
E150A	38/40	1 1/2	
E200A	50	2	
E250A	63/65	2 1/2	
E300A	75	3	
E400A	100	4	
D50A	13	1/2	
D75/50A	19 - 13	3/4 - 1/2	
D75A	19	3/4	
D100A	25	1	
D125A	32	1 1/4	
D150A	38/40	1 1/2	
D200A	50	2	
D250A	63/65	2 1/2	
D300A	75	3	
D400A	100	4	
B50A	13	1/2	
B75/50A	19 - 13	3/4 - 1/2	
B75A	19	3/4	
B100A	25	1	
B125A	32	1 1/4	
B150A	38/40	1 1/2	
B200A	50	2	
B250A	63/65	2 1/2	
B300A	75	3	
B400A	100	4	

Kods	mm	"	Skice
C50A	13	1/2	
C75/50A	19 - 13	3/4 - 1/2	
C75A	19	3/4	
C100A	25	1	
C125A	32	1 1/4	
C150A	38/40	1 1/2	
C200A	50	2	
C250A	63/65	2 1/2	
C300A	75	3	
C400A	100	4	
DP50A	13	1/2	
DP75A	19	3/4	
DP100A	25	1	
DP125A	32	1 1/4	
DP150A	38/40	1 1/2	
DP200A	50	2	
DP250A	63/65	2 1/2	
DP300A	75	3	
DP400A	100	4	
DC50A	13	1/2	
DC75A	19	3/4	
DC100A	25	1	
DC125A	32	1 1/4	
DC150A	38/40	1 1/2	
DC200A	50	2	
DC250A	63/65	2 1/2	
DC300A	75	3	
DC400A	100	4	
MB50MS	50	2	
MB80MS	75	3	
VK50MS	50	2	
VK80MS	75	3	
VK100MS	100	4	
VB50MS	50	2	
VB80MS	75	3	
MK50MS	50	2	
MK80MS	75	3	
MK100MS	100	4	
23AL	50	2	
24AL	75	3	
2" Ax3" C AL	50/75		
3" Ax4" C AL	75/100		



Zāļu iela 4, Rīga
Tel. 7627201 Mob.tel. 9210496
E-mail: baltcontrol@baltcontrol.lv
www.baltcontrol.lv



Vairoga iela 1/5, Rīga
Tel. 7840201 Mob.tel. 8621000
E-mail: baltcontrol@baltcontrol.lv
www.baltcontrol.lv